

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 118135  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37750

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [ Nellis A.F.B. ]  
MAILING ADDRESS Washington DC Subdivision Name: \_\_\_\_\_ County: Clark  
2 LOCATION SW ¼ SW ¼ Sec 3 T 20S N/S R 62 E Latitude 36.234255 UTM E  NAD 27  
PERMIT/WAIVER No. H-000078 140-03-301-001 Longitude 115.040380 N  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log? no  
 Domestic  Irrigation  Test  No  Yes  
 Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 66 Feet Depth Cased 66 Feet  
EXISTING CASING SCHEDULE  
Size O.D. (Inches) Weight/Ft. (Pounds) Wall Thickness (Inches) From (Feet) To (Feet)  
4 pvc 40sch 0 66

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: try to pull casing and knocked out bottom

Existing Perforations:  
Type of perforation Factory  
Size of perforation 0.02  
From 36 feet to 66 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 43 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 20 feet to 65 feet  quik grout  Pumped  Poured  
From 0 feet to 20 feet  concrete mix  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
try to pull casing  
DCNR/DWR/SNRC  
RECEIVED knocked out bottom  
SEP 17 2013  
tremied  
filled from botton  
to top  
3961302 44mw-21

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/15/2013  
Date Completed 8/15/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor  
Nevada contractor's license number 51266  
issued by the State Contractor's Board  
Nevada driller's license number issued by the 2097  
Division of Water Resources, the on-site driller  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 8/21/2013

USE ADDITIONAL SHEETS IF NECESSARY

(Rev. 05-06)

36.2342541 NAD 27  
-115.0393451