

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118140
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37748

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [Nellis A.F.B.]
MAILING ADDRESS Washington DC
Subdivision Name: _____ County: Clark

2 LOCATION SW ¼ NE ¼ Sec 3 T 20S N/S/R 62 E Latitude 36.243132 UTM E _____ NAD 27
PERMIT/WAIVER No. H-000078 140-03-501-001 Longitude 115.030933 N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? _____
If yes, what is replacement well NOI? _____
Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 79.5 Feet Depth Cased 79.5 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>6</u>	<u>pvc</u>	<u>40sch</u>	<u>0</u>	<u>79.5</u>

Existing Perforations:

Type of perforation	Factory
Size of perforation	<u>0.02</u>
From <u>49.5</u> feet to <u>79.5</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL
Static water level 45 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
try to pull casing
knocked out bottom
DCNR/DWR/SNBO RECEIVED
SEP 17 2013
tremied
filled from botton
to top
3961302 28ew-54

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used: try to pull casing and knocked out bottom

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>20</u>	feet to <u>79.5</u>	feet	quik grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From <u>0</u>	feet to <u>20</u>	feet	concrete mix	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite
Date Started 8/115/2013
Date Completed 8/15/2013

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling LLC. Contractor
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor
Nevada contractor's license number _____ issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097
Signed _____
By Driller performing actual drilling on site or contractor
Date 8/21/2013

USE ADDITIONAL SHEETS IF NECESSARY

36.2431611 NAD 27
-115.0300936