

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 118142  
Permit No. \_\_\_\_\_  
Basin 210

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37748

1 OWNER USA ADDRESS AT WELL LOCATION Sunrise Manor [ Nellis A.F.B. ]  
MAILING ADDRESS Washington DC Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ NE ¼ Sec 3 T 20S N/S R 62 E Latitude 36.242650 UTM E  NAD 27  
PERMIT/WAIVER No. H-000078 140-03-501-001 Longitude 115.031400 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log? no  
 Domestic  Irrigation  Test  Stock  
 Municipal/Industrial  Monitor  Stock  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 79.5 Feet Depth Cased 79.5 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6	pvc	40sch	0	79.5

Existing Perforations:  
Type of perforation Factory  
Size of perforation 0.02  
From 49.5 feet to 79.5 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: try to pull casing and knocked out bottom

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

5 WATER LEVEL  
Static water level 45 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used			
From <u>20</u> feet to <u>79.5</u> feet	quik grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>0</u> feet to <u>20</u> feet	concrete mix	<input type="checkbox"/> Pumpe	<input checked="" type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____ feet to _____ feet	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

6 Additional Notes or Comments  
try to pull casing  
knocked out bottom  
DCNR/DWR/SNBG RECEIVED  
SEP 17 2013  
tremied  
filled from botton  
to top  
3961302 28ew-52

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/15/2013  
Date Completed 8/15/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor  
Nevada contractor's license number issued by the State Contractor's Board 31266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
Date 8/21/2013  
By driller performing actual drilling on site or contractor