

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 118145  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37748

1 OWNER USA  
MAILING ADDRESS Washington DC

ADDRESS AT WELL LOCATION Sunrise Manor [ Nellis A.F.B. ]  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ NE ¼ Sec 3 T 20S N/S R 62 E  
PERMIT/WAIVER No. H-000078 140-03-501-001  
Issued by Water Resources Parcel No.

Latitude 36.241657 UTM E  NAD 27  
Longitude 115.032473 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? no  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 79.5 Feet Depth Cased 79.5 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6	pvc	40sch	0	79.5

If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

From	Type of perforation	Size of perforation	Factory	To
From		49.5	0.02	79.5
From				
From				
From				

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: try to pull casing and knocked out bottom

From	feet to	feet	Number of perfs per linear foot
From			

5 WATER LEVEL  
Static water level 45 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used

From	feet to	feet	Material	Applied
From	20	79.5	quik grout	<input checked="" type="checkbox"/> Pumped <input type="checkbox"/> Poured
From	0	20	concrete mix	<input type="checkbox"/> Pumpe <input checked="" type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
From				<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments  
try to pull casing  
knocked out bottom  
DCNR/DWR/SNBC RECEIVED  
SEP 17 2013 filled from botton  
to top  
3961302 28ew-49

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/16/2013  
Date Completed 8/16/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor  
Nevada contractor's license number \_\_\_\_\_ issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 8/21/2013