

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 118146
 Permit No. _____
 Basin 212

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37748

1 OWNER USA
 MAILING ADDRESS Washington DC

ADDRESS AT WELL LOCATION Sunrise Manor [Nellis A.F.B.]

Subdivision Name: _____ County: Clark

2 LOCATION SW ¼ NE ¼ Sec 3 T 20S N/S R 62 E
 PERMIT/WAIVER No. H-000078 140-03-501-001
Issued by Water Resources Parcel No.

Latitude 36.241342 UTM E NAD 27
 Longitude 115.032815 N NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? _____
 Is there an existing well log? no
 If yes, what is replacement well NOI? _____
 If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 80 Feet Depth Cased 80 Feet

7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6	pvc	40sch	0	80

If well was not cleaned out to total depth, please explain why: _____

Existing Perforations:

From	Type of perforation	Size of perforation	Factory	To
From	50	feet to	80	feet
From		feet to		feet
From		feet to		feet
From		feet to		feet

Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:

From	Type of perforater used:	To	Number of perfs per linear foot
From	try to pull casing and knocked out bottom	feet	
From		feet	

5 WATER LEVEL
 Static water level 45 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ ° F Quality _____

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments
try to pull casing
knocked out bottom
 DCNR/DWR/SNBC
 RECEIVED
SEP 17 2013 tremied
filled from botton
to top
3961302 28ew-48

Material Used

From	To	Material	Pumped	Poured
From	20	feet to 80 feet quik grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From	0	feet to 20 feet concrete mix	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From		feet to feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to feet	<input type="checkbox"/>	<input type="checkbox"/>
From		feet to feet	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 8/16/2013
 Date Completed 8/16/2013

9 DRILLER'S CERTIFICATION
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Eagle Drilling LLC. Contractor
 Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor
 Nevada contractor's license number issued by the State Contractor's Board 51266
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097
 Signed [Signature]
 Date 8/21/2013

USE ADDITIONAL SHEETS IF NECESSARY

36,2413711 NAD 27
 -115.0319826

(Rev. 05-06)