

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118203
Permit No. _____
Basin 101

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 71048

1 OWNER Doug Lewis ADDRESS AT WELL LOCATION 6262 Lakeview Drive
MAILING ADDRESS 6262 Lakeview Drive Fallon, NV 89406
Subdivision Name: _____ County: Churchill

2 LOCATION NE ¼ SE ¼ Sec 18 T 19N N/S/R 28 E Latitude 39.50974 N UTM E NAD 27
PERMIT/WAIVER No. 008-113-20 Longitude 118.87996 W N NAD 83/WGS 84
Issued by Water Resources Parcel No. _____

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? Is there an existing well log?
 Domestic Irrigation Test Yes Yes
 Municipal/Industrial Monitor Stock If yes, what is replacement well NOI? 71047 If yes, what is NDWR well log #? 96277

4 EXISTING WELL CONSTRUCTION
Depth Drilled 95 Feet Depth Cased 95 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 5/8	12.92	0.188	0	95

Existing Perforations:

Type of perforation	Machine
Size of perforation	0.08
From <u>89</u> feet to <u>93</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL
Static water level 23 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature Cool °F Quality Unknown

6 Additional Notes or Comments
Pumped 20% Bentonite grout from 95 to 20 ft.
Neat Cement from 20 ft to surface.

RECEIVED
 DIVISION OF WATER RESOURCES
 6262 LAKEVIEW DRIVE
 FALLON, NV 89406
 775-778-1100

NAD 27
 39.509824 N
 118.878971 W
 Plugs well log 96277

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:

Type of perforator used:	Mill Knife
From <u>50</u> feet to <u>88</u> feet	Number of perfs per linear foot <u>6</u>
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____
From _____ feet to _____ feet	Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>95</u>	feet to <u>20</u>	Bentonite	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From <u>20</u>	feet to <u>0</u>	Neat cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.6 lbs/gal
Bentonite Grout 20 % bentonite
Date Started 9/29/2013 08/29/2013
Date Completed 9/29/2013 08/29/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Parsons Drilling, Inc
Contractor
Address P.O. Box 1265
Contractor
Fallon, NV 89407

Nevada contractor's license number issued by the State Contractor's Board 29064

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1753-T2

Signed [Signature]
By driller performing actual drilling on site or contractor
Date 9/12/2013