

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118321
Permit No. _____
Basin 054

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 69993 ✓

1 OWNER cortez gold mine
MAILING ADDRESS HC 66 box 1250
Crescent Valley 89821

ADDRESS AT WELL LOCATION _____
CHSI 2
Subdivision Name: _____
County: Lander

2 LOCATION SE ¼ NE ¼ Sec 31 T 27N N/S R 48 E
PERMIT/WAIVER No. M/O1745
Issued by Water Resources Parcel No. _____

Latitude _____ UTM E 534277 NAD 27
Longitude _____ N 4446305 NAD 83/WGS 84

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? yes
If yes, what is NDWR well log #? 115563

4 EXISTING WELL CONSTRUCTION
Depth Drilled 400 Feet Depth Cased 400 Feet

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2.75	.99		+1	400

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

Existing Perforations:
Type of perforation none
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: none

5 WATER LEVEL
Static water level n/a feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

From	feet to	feet	Number of perfs per linear foot

6 Additional Notes or Comments

8 WELL PLUGGING MATERIALS

there was cement grout on outside of casing to depth
CHSI-02
RECEIVED
20 MAR 18 AM 11:00
STATE ENGINEERS OFFICE
NAD 27 40.169305°N
116.597462°W

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
1	400	feet	cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.4 lbs/gal
Bentonite Grout _____ % bentonite
Date Started dec 15 2012
Date Completed dec 15 2012

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name National EWP Contractor
Address 500 W Silver St Contractor
Eiko, NV 89801
Nevada contractor's license number _____
issued by the State Contractor's Board 0075355
Nevada driller's license number issued by the _____
Division of Water Resources, the on-site driller 2385
Signed [Signature]
By driller performing actual drilling on site or contractor
Date 3/10/13

(Rev. 05-08)

USE ADDITIONAL SHEETS IF NECESSARY