

STATE OF NEVADA
 DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
 Log No. 115366
 Permit No. _____
 Basin 101

PRINT OR TYPE ONLY
 DO NOT WRITE ON BACK

Please complete this form in its entirety in
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 69175-9

1 OWNER A&K Earthmovers, Inc ADDRESS AT WELL LOCATION New Frontier River Parkway
 MAILING ADDRESS P.O. Box 1059 Fallon, NV 89406
Fallon, NV 89407 Subdivision Name: _____ County: Churchill

2 LOCATION SE ¼ SW ¼ Sec 32 T 19N N/S/R 29 E Latitude 39.46314 N UTM E NAD 27
 PERMIT/WAIVER No. DW-098 A 001-781-21 Longitude 118.75382 W N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? yes
 Domestic Irrigation Test Stock If yes, what is replacement well NOI? _____ If yes, what is NDWR well log #? 117660
 Municipal/Industrial Monitor Stock

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8.625	8.26	.508	0	30

Existing Perforations:

Type of perforation	Well Screen
Size of perforation	0.032
From <u>10</u> feet to <u>30</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL
 Static water level 7 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature Cool °F Quality unknown

6 Additional Notes or Comments

Pumped neat cement from 30' to top of hole.

RECEIVED
 2013 OCT 29 PM 12:10
 STATE ENGINEERS OFFICE

Plugs well log 115366
 NAD 83
 39.4632220N
 118.753836W

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: _____
 Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
 Additional Perforations:
 Type of perforator used: N/A

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____
From _____	feet to _____	feet	Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>0</u>	feet to <u>30</u>	feet	Neat Cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet		<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet		<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet		<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet		<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	feet		<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight 15.6 lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 9/30/2013
 Date Completed 9/30/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Parsons Drilling, Inc Contractor
 Address P.O. Box 1265 Contractor
Fallon, NV 89407

Nevada contractor's license number issued by the State Contractor's Board 29064
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2285

Signed Wayne By driller performing actual drilling on site or contractor
 Date 10/7/2013