

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 118441  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 36955

1 OWNER Public ROW ADDRESS AT WELL LOCATION Public ROW on Vegas Dr.  
MAILING ADDRESS 500 South Grand Central Pkwy west of Siver Lake  
Las Vegas Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NE ¼ NE ¼ Sec 30 T 20S N/S R 61 E Latitude N 26770436.82 UTM E  NAD 27  
PERMIT/WAIVER No. DW-1328 13930599002 Longitude E 771445.5317 N  NAD 83/WGS 84

Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 30 Feet Depth Cased 30 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	30

Existing Perforations:

Type of perforation	Size of perforation	From	To
machine slotted	0.032	10	30
From	feet to		feet
From	feet to		feet
From	feet to		feet
From	feet to		feet

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

6 Additional Notes or Comments

**DW #8**

**DCNR/DWR/SNBO  
RECEIVED  
NOV 01 2013**

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From	2	12	concrete grout	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 8/28/2013  
Date Completed 8/28/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Viking Drillers Inc  
Contractor  
Address 5950 Granite Lake Drive  
Contractor  
Granite Bay, CA 95746

Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680

Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller M2090

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 9/30/2013