

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119501  
Permit No. \_\_\_\_\_  
Basin 105

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 69881

1 OWNER A&A Construction  
MAILING ADDRESS P.O. Box 995  
Minden, NV. 89423

ADDRESS AT WELL LOCATION Near intersection of Lasso Lane and  
Heybourne Road in Gardnerville, NV  
Subdivision Name: The Ranch @ Gardnerville County: Douglas

2 LOCATION SW 1/4 NW 1/4 Sec 33 T 13N N/S R 20 E  
PERMIT/WAIVER No. \_\_\_\_\_  
Issued by Water Resources Parcel No.

Latitude 38 56.900 N UTM E  NAD 27  
Longitude 119 118 45.001 W N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 106266

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 20 Feet Depth Cased 19 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
10	8.68	.413	0	19

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	To
hand slotted	1/4"	10 feet	20 feet

Type of perforator used:

From	To	Number of perfs per linear foot

5 WATER LEVEL  
Static water level 6' feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	To	Material Used	Pumped	Poured
0	20	neat cement	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
No pump in well. Installed tremmie, pumped in neat cement and pulled casing from well.

Neat Cement Fluid Weight 14.5 lbs/gal  
Bentonite Grout % bentonite  
Date Started 10/7/2013  
Date Completed 10/9/2013

# DW-14  
NAD 27  
38.948333° N  
119.152017° W  
plug well log  
10/2/13  
2013 NOV 5 PM 2:00  
DIVISIONERS OFFICE

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Carson Pump, LLC Contractor  
Address P.O. Box 20159 Contractor  
Carson City, NV, 89721  
Nevada contractor's license number issued by the State Contractor's Board 39920A  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2265  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 10/22/2013

(Rev. 05/06)

**USE ADDITIONAL SHEETS IF NECESSARY**