

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY

Log No. 114653

Permit No. _____

Basin 701

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. _____

1 OWNER Global Exploration Services, Ltd. ADDRESS AT WELL LOCATION APPROX 5 MILES SOUTH OF I-80/US 95 JUNCTION

MAILING ADDRESS 2689 Highway 20 Marysville, CA 95901 Subdivision Name: _____ County: Churchill

2 LOCATION NW 1/4 NW 1/4 Sec 17 T 23N N3R 29 E Latitude 39.86689 UTM E _____ NAD 27

PERMIT/WAIVER No. 004-431-09 Longitude -118.75467 N _____ NAD 83/WGS 84

Issued by Water Resources Parcel No.

3 TYPE OF WELL

Domestic Irrigation Test Stock

Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? NO

If yes, what is replacement well NOR? _____

Is there an existing well log? NO

If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION

Depth Drilled 50 Feet Depth Cased 0 Feet

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| <u>NA</u> | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth? yes no

If well was not cleaned out to total depth, please explain why: Cased in at bottom or material fell in

Was the well contaminated? yes no

Was the casing pulled? yes no

Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:

Existing Perforations:

Type of perforation NA

Size of perforation NA

From _____ feet to _____ feet

Additional Perforations:

Type of perforator used: NA

From NA feet to NA feet Number of perfs per linear foot NA

From _____ feet to _____ feet Number of perfs per linear foot _____

From _____ feet to _____ feet Number of perfs per linear foot _____

From _____ feet to _____ feet Number of perfs per linear foot _____

From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL

Static water level none feet below land surface

Artesian flow none G.P.M. none P.S.I.

Water temperature _____ ° F Quality _____

8 WELL PLUGGING MATERIALS

| From | feet to | feet | Material Used | Pumped | Poured |
|------------|------------|------------|------------------------|--------------------------|-------------------------------------|
| <u>48'</u> | <u>20'</u> | <u>20'</u> | <u>native material</u> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| <u>20'</u> | <u>TOP</u> | <u>TOP</u> | <u>cement</u> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |
| | | | | <input type="checkbox"/> | <input type="checkbox"/> |

6 Additional Notes or Comments

BH #6

hole depth 50'

measured depth 48'

cased in at bottom or material fell in

Neat Cement Fluid Weight _____ lbs/gal

Bentonite Grout _____ % bentonite

Date Started 11-14-13

Date Completed 11-14-13

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Matthew L. Linnick

Address Marysville Cal 95901

2689 Highway 20

Nevada contractor's license number _____ issued by the State Contractor's Board

Nevada driller's license number issued by the Division of Water Resources, the on-site driller _____

Signed _____

Date _____

plugs with grout well log

NA027

39.86689 N

118.753693 W

By driller performing actual drilling on site or contractor