

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 1196054

Permit No. \_\_\_\_\_

Basin IC1

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. \_\_\_\_\_

1 OWNER Global Exploration Services, Ltd.  
MAILING ADDRESS 2689 Highway 20 Marysville, CA 95901

ADDRESS AT WELL LOCATION APPROX. 5 MILES SOUTH OF I-80/US 95 JUNCTION

2 LOCATION N 1/4 NW 1/4 Sec 17 T 23N NSR 29 E  
PERMIT/WAIVER No. 004-431-09  
Issued by Water Resources Parcel No.

Subdivision Name: \_\_\_\_\_ County: Churchill  
Latitude 39.86739 UTM E  NAD 27  
Longitude -118.75230 N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? NO  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled 38 Feet Depth Cased 0 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>NA</u>	<u>—</u>	<u>—</u>	<u>—</u>	<u>—</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation NA  
Size of perforation N/A

From	feet to	feet
From	feet to	feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: NA

From	feet to	feet	Number of perfs per linear foot
From <u>NA</u>	feet to <u>NA</u>	feet	<u>NA</u>
From	feet to	feet	
From	feet to	feet	
From	feet to	feet	
From	feet to	feet	
From	feet to	feet	

5 WATER LEVEL

Static water level none feet below land surface  
Artesian flow none G.P.M. none P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From <u>38'</u>	feet to <u>20'</u>	feet	<u>native material</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From <u>20'</u>	feet to <u>TOP</u>	feet	<u>cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>
From	feet to	feet		<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

BL # 7

hole depth 38'  
measured depth 38'

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 11-14-13  
Date Completed 11-14-13

Vertical text on left side: **STATE OF NEVADA DIVISION OF WATER RESOURCES**

plugs unknown well log

NAD 27  
39.867438° N  
118.751313° W

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name W. A. Carvel Contractor  
Address Marysville, Cal 95901 Contractor  
Nevada contractor's license number 2689 Highway 20  
Issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller \_\_\_\_\_

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor

Date \_\_\_\_\_