

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 1186510  
Permit No. \_\_\_\_\_  
Basin (C)

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. \_\_\_\_\_

1 OWNER Global Exploration Services, Ltd. ADDRESS AT WELL LOCATION APPROX. 5 MILES SOUTH OF I-80/US 95 JUNCTION  
MAILING ADDRESS 2689 Highway 20 Marysville, CA 95901 Subdivision Name: \_\_\_\_\_ County: Churchill

2 LOCATION SW 1/4 NW 1/4 Sec 17 T 23N N/S R 29 E Latitude 39.86337 LITME  NAD 27  
PERMIT/WAIVER No. 004-481-09 Longitude -118.75416 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? NO  
If yes, what is replacement well NO? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 62 Feet Depth Cased 0 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/FL (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>NA</u>				

Existing Perforations:  
Type of perforation NA  
Size of perforation NA  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: NA  
From NA feet to NA feet Number of perfs per linear foot NA  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level None feet below land surface  
Artesian flow None G.P.M. None P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	Pumped	Poured
<u>62'</u>	<u>20'</u>	<u>native material</u>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<u>20'</u>	<u>TOP</u>	<u>CEMENT</u>	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

8 Additional Notes or Comments  
3H #9  
hole depth 62'  
measured depth 62'  
plugs unknown well log  
NAD27  
39.863458°N  
118.753773°W

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite

Date Started 11-14-13  
Date Completed 11-14-13

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Robert W. Carrick Contractor  
Address Marysville CA 95901 Contractor  
2689 Highway 20  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date \_\_\_\_\_