

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 115657

Permit No. \_\_\_\_\_

Basin C1

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. \_\_\_\_\_

1 OWNER Global Exploration Services, Ltd.  
MAILING ADDRESS 2689 Highway 20 Marysville, CA 95901

ADDRESS AT WELL LOCATION APPROX. 5 MILES SOUTH OF  
I-80/W 95 JUNCTION

Subdivision Name: \_\_\_\_\_ County: Churchill

2 LOCATION SE 1/4 NW 1/4 Sec 17 T 23N N/SR 29 E  
PERMIT/WAIVER No. 004-431-09  
Issued by Water Resources Parcel No.

Latitude 39.86323 UTM E \_\_\_\_\_  NAD 27  
Longitude -118.75200 N \_\_\_\_\_  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? NO  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 62 Feet Depth Cased 0 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>N/A</u>				

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: N/A

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>N/A</u>	<u>N/A</u>			

From	feet to	feet	Number of perfs per linear foot
<u>N/A</u>	<u>N/A</u>		<u>N/A</u>

5 WATER LEVEL  
Static water level NONE feet below land surface  
Artesian flow NONE G.P.M. NONE P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

6 Additional Notes or Comments  
BH #10  
hole depth 62' measured depth 62'

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>62'</u>	<u>20'</u>	<u>20'</u>	<u>native material</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<u>20'</u>	<u>top</u>	<u>top</u>	<u>Cement</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11-14-13  
Date Completed 11-14-13

CONTRACTOR'S SIGNATURE  
 CONTRACTOR'S NAME  
 CONTRACTOR'S ADDRESS  
 CONTRACTOR'S PHONE NUMBER  
 CONTRACTOR'S LICENSE NUMBER  
 CONTRACTOR'S STATE  
 CONTRACTOR'S CITY  
 CONTRACTOR'S ZIP CODE  
 CONTRACTOR'S COUNTY

plug unknown well log

NAD27  
39.464018°N  
116.751013°W

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Matthew Sivilich Contractor  
Address Marysville, CA 95901 Contractor  
2689 Highway 20  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller  
Signed \_\_\_\_\_  
Date \_\_\_\_\_  
By driller performing actual drilling on site or contractor

(Rev. 05-06)

**USE ADDITIONAL SHEETS IF NECESSARY**