

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 113069  
Permit No. \_\_\_\_\_  
Basin OTS

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67816

1 OWNER MOLTAN CO ADDRESS AT WELL LOCATION I-80 EAST EXIT 68  
MAILING ADDRESS I-80 EAST EXIT 68 FERNLEY, NV 89408  
FERNLEY, NV 89408 Subdivision Name: \_\_\_\_\_ County: Churchill

2 LOCATION SE 1/4 SE 1/4 Sec 29 T 23N N/S R 27 E Latitude 39.82746°N UTM E  NAD 27  
PERMIT/WAIVER No. R-716 004-391-32 Longitude 118.96949°W N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? YES  
Is there an existing well log? YES  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? 27436

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 589 Feet Depth Cased 589 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8 5/8	15.65	.188	0	589

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: CASING COLLAPSED DOWN ABOUT 120' FROM THE TOP OF THE WELL AFTER CLEANING POUT WELL  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
N/A	N/A			

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot
N/A	N/A			

5 WATER LEVEL  
Static water level 420 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature COLD °F Quality POOR

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
0	122	feet	NEAT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
THE NEAT CEMENT WOULD NOT MIGRATE PAST THE 120' OBSTRUCTION IN THE WELL

Neat Cement Fluid Weight 94/4 lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11/13/2012  
Date Completed 11/13/2012

*plug well log 27436*

REC'D  
SUBJECT: 11/15/12  
STATE ENGINEER'S OFFICE  
NAD 27  
39.82746°N  
118.96949°W

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name CAPITAL CITY WELL DRILLING AND PUMP SERVICE INC. Contractor  
Address 20 KIT KAT DRIVE Contractor  
CARSON CITY, NV 89706  
Nevada contractor's license number 0055548  
issued by the State Contractor's Board  
Nevada driller's license number issued by the 1905  
Division of Water Resources, the on-site driller  
Signed [Signature] By driller performing actual drilling on site or contractor  
Date 11/24/2012

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY