

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 118705  
 Permit No. \_\_\_\_\_  
 Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37699

1 OWNER ATI Service LLC ADDRESS AT WELL LOCATION Sunrise Manor  
 MAILING ADDRESS 301 N. Lake St#600 IW-1  
Pasadena, CA 91101-5129 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SE ¼ NE ¼ Sec 1 T 21S N/S R 61 E Latitude 36 09'09.64"N UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 162-01-602-016 Longitude 115 06'04.81"W N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
 Is this well being plugged because a replacement well was drilled? No  
 If yes, what is replacement well NOI? \_\_\_\_\_  
 Is there an existing well log? N/A  
 If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 15 Feet Depth Cased \_\_\_\_\_ Feet  
 EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5		Sch 40	0	15

Existing Perforations:  
 Type of perforation Factory Slotted  
 Size of perforation 0.02

From	feet to	feet	feet
From <u>5</u>	feet to	<u>15</u>	feet
From _____	feet to	_____	feet
From _____	feet to	_____	feet
From _____	feet to	_____	feet
From _____	feet to	_____	feet

5 WATER LEVEL  
 Static water level 13 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments

**DCNR/DWR/SNBO  
RECEIVED  
NOV 08 2013**

7 WELL PLUGGING PROCEDURE  
 Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:  
 Type of perforator used: \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot
From _____	feet to	_____	_____
From _____	feet to	_____	_____
From _____	feet to	_____	_____
From _____	feet to	_____	_____
From _____	feet to	_____	_____
From _____	feet to	_____	_____

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	Pumped	Poured
From <u>0</u>	feet to	<u>1</u>	Concrete	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
From <u>1</u>	feet to	<u>15</u>	Cement Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to	_____	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to	_____	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to	_____	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From _____	feet to	_____	_____	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 10/29/2013  
 Date Completed 10/29/2013

9 DRILLER'S CERTIFICATION  
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
 Name Cascade Drilling L.P. Contractor  
 Address 4590 Copper Sage St Contractor  
Las Vegas, NV 89115  
 Nevada contractor's license number issued by the State Contractor's Board C23-0073966  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2381  
 Signed \_\_\_\_\_  
 By driller performing actual drilling on site or contractor  
 Date 11-8-13

(Rev. 05-06) USE ADDITIONAL SHEETS IF NECESSARY

36, 1527061 NAD 27  
 - 115, 1005035