

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY

Log No. 118707

Permit No. _____

Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37699

1 OWNER ATI Service LLC ADDRESS AT WELL LOCATION Sunrise Manor
 MAILING ADDRESS 301 N. Lake St#600 MW-1
Pasadena, CA 91101-5129 Subdivision Name: _____ County: Clark

2 LOCATION SE 1/4 NE 1/4 Sec 1 T 21S N/S R 61 E Latitude 36 09'07.86"N UTM E NAD 27
 PERMIT/WAIVER No. 162-01-602-016 Longitude 115 06'04.46"W N NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
 Is this well being plugged because a replacement well was drilled? No
 Is there an existing well log? N/A
 If yes, what is replacement well NO? _____ If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 10 Feet Depth Cased _____ Feet
 EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4.5		Sch 40	0	10

7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: _____
 Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no
 If casing was left in place, please show where additional perforations were made: _____

Existing Perforations:
 Type of perforation _____ Factory Slotted _____
 Size of perforation _____ 0.02 _____
 From 5 feet to 10 feet
 From _____ feet to _____ feet

Additional Perforations:
 Type of perforator used: _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____
 From _____ feet to _____ feet Number of perfs per linear foot _____

5 WATER LEVEL
 Static water level N/A feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ °F Quality _____

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	Pumped	Poured
0	1	Concrete	<input type="checkbox"/>	<input checked="" type="checkbox"/>
1	10	Cement Grout	<input checked="" type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

DCNR/DWR/SNBO
RECEIVED
NOV 03 2013

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout _____ % bentonite
 Date Started 10/29/2013
 Date Completed 10/29/2013

9 DRILLER'S CERTIFICATION
 This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Cascade Drilling L.P. Contractor
 Address 4590 Copper Sage St Contractor
Las Vegas, NV 89115
 Nevada contractor's license number issued by the State Contractor's Board C23-0073966
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2381
 Signed [Signature]
 By driller performing actual drilling on site or contractor
 Date 11-8-13

(Rev. 05-09) USE ADDITIONAL SHEETS IF NECESSARY

36.1522116 NAD 27
-115.1004063