

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 118769
Permit No. _____
Basin 212

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37124

1 OWNER County Of Clark (PK & Comm. Serv.) ADDRESS AT WELL LOCATION 5600 Wiesner Way
MAILING ADDRESS 500 S. Grand Central Prwy. Las Vegas NV. 89122
Las Vegas NV. 89155 Subdivision Name: _____ County: Clark

2 LOCATION SE 1/4 SW 1/4 Sec 25 T 21S N/S R 62 E Latitude 36.085669 UTM E NAD 27
PERMIT/WAIVER No. 161-25-401-001 Longitude -115.007023 N NAD 83/WGS 84

Issued by Water Resources Parcel No. _____

3 TYPE OF WELL
 Domestic Irrigation Test
 Municipal/Industrial Monitor Stock

Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____

Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 35 Feet Depth Cased 35 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>pvc</u>	<u>Sch/40</u>	<u>0</u>	<u>35</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

5 WATER LEVEL
Static water level 19' feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Pulled 2' casing & broken
Knocked Out Bottom
Tremmed From Bottom To TOP
MP-11

DEC 12 2013

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no

If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: Try to pull casing knocked out bottom

From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Bentonite Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>35</u>	<u>0</u>	<u>0</u>			
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
				<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout 20 % bentonite
Date Started 11/20/2013
Date Completed 11/20/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling LLC.
Contractor
Address 7150 Placid St., Las Vegas, Nv., 89119
Contractor

Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2477-M

Signed Paul E. D...
By driller performing actual drilling on site or contractor
Date Dec 5 - 2013

(Rev. 05-06) USE ADDITIONAL SHEETS IF NECESSARY

NAD 36.0856939
27 -115.0061948