

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY

Log No. 118780
 Permit No. _____
 Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37124

1 OWNER County Of Clark (PK & Comm. Serv.) ADDRESS AT WELL LOCATION 5600 Wiesner Way
 MAILING ADDRESS 500 S. Grand Central Prwy. Las Vegas NV. 89122
 Las Vegas NV. 89155
 Subdivision Name: _____ County: Clark

2 LOCATION SE ¼ SW ¼ Sec 25 T 21S N/S/R 62 E Latitude 36.085736 UTM E _____ NAD 27
 PERMIT/WAIVER No. 161-25-401-001 Longitude -115.004453 N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
 Is this well being plugged because a replacement well was drilled? no
 If yes, what is replacement well NOI? _____
 Is there an existing well log? no
 If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
 Depth Drilled 40 Feet Depth Cased 40 Feet


EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4	pvc	Sch/40	0	40

Existing Perforations:

Type of perforation	_____	Size of perforation	_____
From	_____ feet to _____ feet	From	_____ feet to _____ feet
From	_____ feet to _____ feet	From	_____ feet to _____ feet
From	_____ feet to _____ feet	From	_____ feet to _____ feet
From	_____ feet to _____ feet	From	_____ feet to _____ feet

5 WATER LEVEL
 Static water level 10.5 feet below land surface
 Artesian flow _____ G.P.M. _____ P.S.I.
 Water temperature _____ °F Quality _____

6 Additional Notes or Comments
Try to pull, knocked out bottom
Tremied From Bottom To Top
RIT-4


7 WELL PLUGGING PROCEDURE
 Was well cleaned out to total depth? yes no
 If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
 Was the casing pulled? yes no
 Was the casing over drilled? yes no
 If casing was left in place, please show where additional perforations were made:
 Additional Perforations:

Type of perforater used:	_____	Try to pull	_____
From	_____ feet to _____ feet	Number of perfs per linear foot	_____
From	_____ feet to _____ feet	Number of perfs per linear foot	_____
From	_____ feet to _____ feet	Number of perfs per linear foot	_____
From	_____ feet to _____ feet	Number of perfs per linear foot	_____
From	_____ feet to _____ feet	Number of perfs per linear foot	_____

8 WELL PLUGGING MATERIALS

Material Used	From <u>40</u> feet to <u>0</u> feet	Bentonite Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
	From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
	From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
	From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
	From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
 Bentonite Grout 20 % bentonite
 Date Started 11/18/2013
 Date Completed 11/18/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
 Name Eagle Drilling LLC. Contractor
 Address 7150 Placid St., Las Vegas, Nv., 89119 Contractor
 Nevada contractor's license number issued by the State Contractor's Board 51266
 Nevada driller's license number issued by the Division of Water Resources the on-site driller 2490 LTD
 Signed [Signature] By driller performing actual drilling on site or contractor
 Date 12/03/2013