

**STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY
Log No. 118786
Permit No. _____
Basin 212

**PRINT OR TYPE ONLY
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37123

1 OWNER County Of Clark (PK & Comm. Serv.) ADDRESS AT WELL LOCATION 5600 Wiesner Way
MAILING ADDRESS 500 S. Grand Central Prwy. Las Vegas NV. 89122
Las Vegas NV. 89155 Subdivision Name: _____ County: Clark

2 LOCATION SW ¼ SW ¼ Sec 25 T 21S N/S R 62 E Latitude 36.085670 UTM E _____ NAD 27
PERMIT/WAIVER No. 161-25-401-001 Longitude -115.007254 N _____ NAD 83/WGS 84
Issued by Water Resources Parcel No.

3 TYPE OF WELL Domestic Irrigation Test Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? no
If yes, what is NDWR well log #? _____

4 EXISTING WELL CONSTRUCTION
Depth Drilled 35 Feet Depth Cased 35 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4</u>	<u>pvc</u>	<u>Sch/40</u>	<u>0</u>	<u>35</u>

Existing Perforations:
Type of perforation _____
Size of perforation _____
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

5 WATER LEVEL
Static water level 18 feet below land surface
Artesian flow _____ G.P.M. _____ P.S.I.
Water temperature _____ ° F Quality _____

6 Additional Notes or Comments
Try to pull:knocked out bottom
Tremied From Bottom To Top
mpg
NAD/DWR/SND
RECEIVED
DEC 12 2013

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:

Type of perforater used: Try to pull

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Bentonite Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From <u>35</u>	feet to <u>0</u>	feet	Bentonite Grout	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
From	feet to	feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout 20 % bentonite
Date Started 11/18/2013
Date Completed 11/18/2013

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Eagle Drilling LLC. Contractor
Address 7150 Placid St. Las Vegas, Nv., 89119 Contractor
Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD
Signed [Signature] By driller performing actual drilling on site or contractor
Date 12/03/2013

NAD
27
36.0856949
-115.0064258