

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**

Log No. 118816

Permit No. \_\_\_\_\_

Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37109

1 OWNER 99 South MLK LLC ADDRESS AT WELL LOCATION 99 S. Martin Luther King Blvd.  
 MAILING ADDRESS 6994 Lazy Sunset CT. Las Vegas, Nv 89106  
Las Vegas, Nv 89156-7206 Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SW ¼ SE ¼ Sec 28 T 20S N/S R 61 E Latitude 36.174087 UTM E \_\_\_\_\_  NAD 27  
 PERMIT/WAIVER No. 139-28-810-001 Longitude -115.160583 N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
 Is this well being plugged because a replacement well was drilled? no  
 If yes, what is replacement well NOI? \_\_\_\_\_  
 Is there an existing well log? yes  
 If yes, what is NDWR well log #? 113734

4 EXISTING WELL CONSTRUCTION  
 Depth Drilled 25 Feet Depth Cased 25 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>	<u>.70</u>	<u>sch 40</u>	<u>0</u>	<u>25</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet
<u>factory slotted</u>	<u>0.02</u>	<u>10</u>	<u>25</u>	<u>feet</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:

Type of perforater used:

From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
 Static water level 24 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used

From	feet to	feet	Material	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>25</u>	<u>0</u>	<u>feet</u>	<u>quik grout</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments

DCNR/DWR/SNBO  
RECEIVED  
DEC 04 2013

mw-7

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 10/28/2013  
 Date Completed 10/28/2013

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling LLC.  
Contractor

Address 7150 Placid St., Las Vegas, Nv., 89119  
Contractor

Nevada contractor's license number issued by the State Contractor's Board 51266  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD

Signed [Signature]  
By driller performing actual drilling on site or contractor

Date 11/14/2013

**USE ADDITIONAL SHEETS IF NECESSARY**

NAD 27  
 36.1741169  
 -115.1597484