

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 118944  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37737

1 OWNER Titanium Metals Corporation ADDRESS AT WELL LOCATION Unincorp. County  
MAILING ADDRESS P.O.Box 2128 Henderson NV. 89009-7003  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NW 1/4 SE 1/4 Sec 12 T 22S N/S R 62 E Latitude 829064.859 UTM E 829064.859  NAD 27  
PERMIT/WAIVER No. 178-12-701-002 Longitude \_\_\_\_\_ N 26720006.602  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? Yes  
If yes, what is NDWR well log #? 98868

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 46 Feet Depth Cased 46 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>4"</u>	<u>PVC</u>	<u>Sch-80</u>	<u>0</u>	<u>46</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
<u>Mechine Slotted</u>	<u>0.02</u>	<u>20</u>	<u>46</u>		

5 WATER LEVEL  
Static water level 31.4 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ ° F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Bottom was knocked out with aw rod  
Casing was slip joint with o-rings  
wich pulled apart  
Quick grout was pumped from bottom to twenty feet  
below surface then quick grout was poured to surface  
PCNR/DWR/SNRC  
RECEIVED

AUG 19 2013

Facility ID # H-000537

EW 626.03

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforater used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 20 feet to 46 feet Quick Grout  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout 20 % bentonite  
Date Started 8/9/2013  
Date Completed 8/9/2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services, L L C. Contractor  
Address 7150 Placid St. Contractor  
Las Vegas, Nv 89119  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2477-M  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 8-12-13