

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 118962  
Permit No. \_\_\_\_\_  
Basin 049

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37709

1 OWNER Dn. Part E.I. DE Nemore  
MAILING ADDRESS 90 Pop. tax DIV. PO. Box 1039  
Wilmington, DE 19899

ADDRESS AT WELL LOCATION 3 miles East of  
Subdivision Name: Carlin on old us 40  
County: Elko

2 LOCATION S.W. 1/4 SE 1/4 Sec 19 T 33 N R 53 E  
PERMIT/WAIVER No. 100528A 004  
Parcel No. \_\_\_\_\_

Latitude 40° 45' 31.37" N UTM E \_\_\_\_\_  NAD 27  
Longitude 116° 03' 13.83" W N \_\_\_\_\_  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NO? \_\_\_\_\_  
Is there an existing well log? No  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet  
Depth Cased 35.65 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8</u>		<u>Steel</u>	<u>+1</u>	<u>35.65</u>

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:

Existing Perforations:  
Type of perforation N/A  
Size of perforation N/A  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Additional Perforations:  
Type of perforation used: mill pipe  
From 35 feet to 20 feet Number of perfs per linear foot 4  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 25.8 feet below land surface  
Artesian flow N/A G.P.M. N/A P.S.I.  
Water temperature N/A °F Quality N/A

8 WELL PLUGGING MATERIALS  
Material Used  
From 35 feet to 20 feet neat cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments

Neat Cement Fluid Weight 94 lbs/gal 5.2  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11-11-13  
Date Completed 11-13-13

Facility # 001140  
Cement from the bottom to top  
with neat cement

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

DCNR/DWR/SNBO  
RECEIVED

Name Cascade Drilling L.P.  
Contractor  
Address 4590 Copper Sage St  
Contractor  
Las Vegas, NV 89115

DEC 02 2013

Nevada contractor's license issued by the State  
Nevada driller's license r  
Division of Water  
Signed [Signature]  
Date \_\_\_\_\_

Northern Township  
We don't have not on file

NAD 40.725462  
27 -116.05932

USE ADDITIONAL SHEETS