

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 118968  
Permit No. \_\_\_\_\_  
Basin 049

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 37706

1 OWNER Du Pont DE Nemour  
MAILING ADDRESS 91 Prop. tax DIV po Box 1039  
Wilmington, DE 19899

ADDRESS AT WELL LOCATION 3 miles East of  
Carlin on Old us 40  
Subdivision Name: \_\_\_\_\_ County: SIKO

2 LOCATION SW 1/4 SE 1/4 Sec 19 T 33 N34 E  
PERMIT/WAIVER No. 100528A004  
Issued by Water Resources Parcel No. \_\_\_\_\_

Latitude 40°43' 21.58 N UTM E \_\_\_\_\_  NAD 27  
Longitude 116°03' 14.19 W N \_\_\_\_\_  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a  
replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_

Is there an existing well log? no  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 35.4 Feet Depth Cased 35.4 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>PVC</u>	<u>1</u>	<u>35.4</u>

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:  
Type of perforation N/A  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Type of perforator used: Cement in place  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 25.7 feet below land surface  
Artesian flow N/A G.P.M. N/A P.S.I.  
Water temperature N/A °F Quality N/A

8 WELL PLUGGING MATERIALS  
Material Used  
From 35.4 feet to 0 feet cement neat  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
\_\_\_\_\_

Neat Cement Fluid Weight 94 lbs/gal 5.2  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 11-11-13  
Date Completed 11-13-13

attempt to pull casing  
(no go) cement in place  
Well # 3  
DCNR/DWRS/NDRC  
RECEIVED  
DEC 02 2013

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true  
to the best of my knowledge.  
Name Cascade Drilling L.P.  
Contractor  
Address 4590 Copper Sage St  
Contractor  
Las Vegas, NV 89115  
Nevada contractor's license number  
issued by the State Contractor's Board C23-0073966  
Nevada driller's license number issued by the  
Division of Water Resources, the on-site driller 2372  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 11-18-17

USE ADDITIONAL SHEETS IF NECESSARY

NAD  
27  
40.7255203  
- 116.053032