

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
Log No. 119065  
Permit No. \_\_\_\_\_  
Basin 212

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 36284

1 OWNER AMAZING RAINBOW ADDRESS AT WELL LOCATION 7420 S RAINBOW  
MAILING ADDRESS 8120 BAY PINES AVE LAS VEGAS  
LAS VEGAS NV 89128-6769 Subdivision Name: \_\_\_\_\_ County: CLARK

2 LOCATION NW ¼ NW ¼ Sec 11 T 22S N/S R 60 E Latitude N36°03'09.5" UTM E  NAD 27  
PERMIT/WAIVER No. 176-11-117-004 Longitude W115°14'30.5" N  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? NO Is there an existing well log? YES  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NO? \_\_\_\_\_ If yes, what is NDWR well log #? 54393

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>8-5/8</u>	<u>13.6</u>	<u>.156</u>	<u>0</u>	<u>548</u>

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

5 WATER LEVEL  
Static water level 386 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
THE WELL LOG #54393 THAT WE THINK GOES WITH THIS WELL HAD A TOTAL DEPTH @ 600 AND TOP OF LINEN @ 360' WE FOUND TOP OF LINER @ 292 AND BOTTOM OF HOLE @ 548' WE BAILED HOLE FOR TWO HOURS & THAT WAS HARD BOTTOM.

OCNR/DWR/SNBO  
RECEIVED  
JAN 22 2014

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: MILLS KNIFE

From	feet to	feet	Number of perfs per linear foot
<u>292</u>	<u>548</u>		<u>4</u>

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
<u>548</u>	<u>0</u>		<u>CEMENT GROUT</u>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/14/2014  
Date Completed 1/16/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name GREAT BASIN DRILLING Contractor  
Address 1220 MANSE RD Contractor  
PAHRUMP NV 89048  
Nevada contractor's license number issued by the State Contractor's Board 47333  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2485  
Signed [Signature]  
Date 1/17/2014  
By driller performing actual drilling on site or contractor