

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119201  
Permit No. \_\_\_\_\_  
Basin 64

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 68833

1 OWNER Department of the Navy ADDRESS AT WELL LOCATION 500' north of the siren tower 300' south of the Delta runway  
MAILING ADDRESS 4755 Pasture Rd., Fallon, NV Subdivision Name: PI-IW-07 County: Churchill

2 LOCATION NW 1/4 SE 1/4 Sec 22 T 18N N/S R 23 E Latitude 39 24 29.57 N UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 006-011-01 Longitude -118. 42 24.86 W N \_\_\_\_\_  NAD 83/WGS 84  
*Issued by Water Resources Parcel No.*

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NO? \_\_\_\_\_

Is there an existing well log? NA  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

|               |      |             |    |      |
|---------------|------|-------------|----|------|
| Depth Drilled | Feet | Depth Cased | 17 | Feet |
|---------------|------|-------------|----|------|

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 2                  |                     | Sch. 40                 | 0           | 17        |
|                    |                     |                         |             |           |
|                    |                     |                         |             |           |
|                    |                     |                         |             |           |
|                    |                     |                         |             |           |

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: Bottom of the well was tagged

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_

Existing Perforations:

| Type of perforation | Size of perforation | From | feet to | feet |
|---------------------|---------------------|------|---------|------|
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |

Type of perforator used: none

| From | feet to | feet | Number of perfs per linear foot |
|------|---------|------|---------------------------------|
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |

5 WATER LEVEL

Static water level 7.5 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

| From | feet to | feet | Material Used | Neat                                     | Neat                            |
|------|---------|------|---------------|--|---------------------------------|
| 0    | feet to | 17   | feet          | <input checked="" type="checkbox"/> Pump | <input type="checkbox"/> Poured |
|      |         |      |               | <input type="checkbox"/> Pumped          | <input type="checkbox"/> Poured |
|      |         |      |               | <input type="checkbox"/> Pumped          | <input type="checkbox"/> Poured |
|      |         |      |               | <input type="checkbox"/> Pumped          | <input type="checkbox"/> Poured |
|      |         |      |               | <input type="checkbox"/> Pumped          | <input type="checkbox"/> Poured |
|      |         |      |               | <input type="checkbox"/> Pumped          | <input type="checkbox"/> Poured |

6 Additional Notes or Comments

completion was pulled and filled with native soil

plugs unknown log

Nad 27  
39.408295 N  
118.53924 W

Neat Cement Fluid Weight 13 gal lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/20/2014  
Date Completed 1/20/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name National EWP Contractor  
Address 500 Main St. Woodland, CA 95695 Contractor  
Nevada contractor's license number 0075355  
issued by the State Contractor's Board  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2111  
Signed [Signature]  
Date 1-27-14  
By driller performing actual drilling on site or contractor

(Rev. 35-06)

**USE ADDITIONAL SHEETS IF NECESSARY**