

STATE OF NEVADA  
 DIVISION OF WATER RESOURCES  
**WELL DRILLER'S PLUGGING REPORT**

OFFICE USE ONLY  
 Log No. 19243  
 Permit No. \_\_\_\_\_  
 Basin 161

PRINT OR TYPE ONLY  
 DO NOT WRITE ON BACK

Please complete this form in its entirety in  
 accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 68833

1 OWNER Department of the Navy ADDRESS AT WELL LOCATION \_\_\_\_\_  
 MAILING ADDRESS 4755 Pasture Rd., Fallon, NV 500' north of the siren tower 300' south of the Delta runway  
 Subdivision Name: BS1-24 County: Churchill

2 LOCATION NE ¼ SE ¼ Sec 22 T 18N N/S R 23 E Latitude 39 24 31.42 N UTM E  NAD 27  
 PERMIT/WAIVER No. 1006-611-01 Longitude -118. 42 28.53 W N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? NA  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

|               |      |             |    |      |
|---------------|------|-------------|----|------|
| Depth Drilled | Feet | Depth Cased | 10 | Feet |
|---------------|------|-------------|----|------|

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|--------------------|---------------------|-------------------------|-------------|-----------|
| 2                  |                     | Sch. 40                 | 0           | 10        |

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
 If well was not cleaned out to total depth, please explain why:  
Bottom of the well was tagged

Existing Perforations:

| Type of perforation | Size of perforation | From | feet to | feet |
|---------------------|---------------------|------|---------|------|
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |
|                     |                     |      |         |      |

Was the well contaminated?  yes  no  
 Was the casing pulled?  yes  no  
 Was the casing over drilled?  yes  no  
 If casing was left in place, please show where additional perforations were made:  
 Additional Perforations:  
 Type of perforator used: none

| From | feet to | feet | Number of perfs per linear foot |
|------|---------|------|---------------------------------|
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |
|      |         |      |                                 |

5 WATER LEVEL

Static water level 8.7 feet below land surface  
 Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
 Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

| From | feet to | feet | Material Used | Neat | <input checked="" type="checkbox"/> Pumped | <input type="checkbox"/> Poured |
|------|---------|------|---------------|------|--|---------------------------------|
| 0    | 10      | 10   |               |      |  |                                 |
|      |         |      |               |      |  |                                 |
|      |         |      |               |      |  |                                 |
|      |         |      |               |      |  |                                 |
|      |         |      |               |      |  |                                 |
|      |         |      |               |      |  |                                 |

6 Additional Notes or Comments  
completion was pulled and filled with native soil  
plug unknown well log  
NAD 83  
39 42 809 N  
118. 42 443 W

Neat Cement Fluid Weight 7 gal lbs/gal  
 Bentonite Grout \_\_\_\_\_ % bentonite  
 Date Started 1/16/2014  
 Date Completed 1/16/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name National EWP Contractor  
 Address 500 Main St. Woodland, CA 95695 Contractor  
 Nevada contractor's license number issued by the State Contractor's Board 0075355  
 Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2111  
 Signed [Signature]  
 Date 1-27-14  
By driller performing actual drilling on site or contractor