

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119252  
Permit No. \_\_\_\_\_  
Basin 19

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 68833

1 OWNER Department of the Navy ADDRESS AT WELL LOCATION 500' north of the siren tower 300' south of the Delta runway  
MAILING ADDRESS 4755 Pastura Rd., Fallon, NV Subdivision Name: BS1-3-3 County: Churchill

2 LOCATION NE ¼ SE ¼ Sec 22 T 18N N/S/R 23 E Latitude 39.24.30.02 N UTM E  NAD 27  
PERMIT/WAIVER No. 1206-011-01 Longitude -118.42.28.12 W N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? NA  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 10 Feet Depth Cased 10 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		Sch. 40	0	10

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Bottom of the well was tagged

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: none  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level 7.6 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used			
From	feet to	feet	Material
0	10	feet	<input checked="" type="checkbox"/> Neat Cement <input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Bentonite Grout <input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured
			<input type="checkbox"/> Pumped <input type="checkbox"/> Poured

6 Additional Notes or Comments  
completion was pulled and filled with native soil  
plugs well log unknown  
Nad 83  
39.409100° N  
118.422830° W

Neat Cement Fluid Weight 5 gal lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/16/2014  
Date Completed 1/16/2014

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name National EWP  
Contractor  
Address 500 Main St. Woodland, CA 95695  
Contractor  
Nevada contractor's license number issued by the State Contractor's Board 0075355  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2111  
Signed [Signature]  
Date 1-27-14  
By driller performing actual drilling on site or contractor