

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119277  
Permit No. \_\_\_\_\_  
Basin 101

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 68833

**1 OWNER** Department of the Navy  
MAILING ADDRESS 4755 Pasture Rd., Fallon, NV  
ADDRESS AT WELL LOCATION 500' north of the siren tower 300' south of the Delta runway  
Subdivision Name: BS1-8 County: Churchill

**2 LOCATION** NE  $\frac{1}{4}$  SE  $\frac{1}{4}$  Sec 22 T 18N N/S R 23 E  
PERMIT/WAIVER No. 1006-011-9  
Latitude 39.24 29.52 N UTM E \_\_\_\_\_  NAD 27  
Longitude -118.42 25.01 W N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

**3 TYPE OF WELL**  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? NA  
If yes, what is NDWR well log #? \_\_\_\_\_

**4 EXISTING WELL CONSTRUCTION**  
Depth Drilled \_\_\_\_\_ Feet Depth Cased 6 Feet

**EXISTING CASING SCHEDULE**

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>Sch. 40</u>	<u>0</u>	<u>6</u>

**7 WELL PLUGGING PROCEDURE**  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
Bottom of the well was tagged  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: \_\_\_\_\_  
Type of perforator used: none

From	feet to	feet	Number of perfs per linear foot

**Existing Perforations:**

Type of perforation	Size of perforation	From	feet to	feet

**Additional Perforations:**

From	feet to	feet	Number of perfs per linear foot

**5 WATER LEVEL**  
Static water level NA feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

**8 WELL PLUGGING MATERIALS**

From	feet to	feet	Material Used	<input checked="" type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
<u>0</u>	<u>6</u>	<u>feet</u>	<u>Neat</u>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>
				<input type="checkbox"/>	<input type="checkbox"/>

**6 Additional Notes or Comments**  
completion was pulled and filled with native soil  
plug with known log  
std 27  
39.408 23.52 N  
118.305 91.06 W

Neat Cement Fluid Weight 3 Gal lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 1/17/2014  
Date Completed 1/17/2014

*2014-03-11 2:00 PM  
DIVISION OF WATER RESOURCES OFFICE*

**9 DRILLER'S CERTIFICATION**  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name National EWP Contractor  
Address 500 Main St. Woodland, CA 95695 Contractor  
Nevada contractor's license number 0075355  
issued by the State Contractor's Board  
Nevada driller's license number issued by the 2111  
Division of Water Resources, the on-site driller  
Signed [Signature]  
By driller performing actual drilling on site or contractor  
Date 1-27-14