

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 119144  
Permit No. \_\_\_\_\_  
Basin 101

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 68839

1 OWNER Department of the Navy ADDRESS AT WELL LOCATION \_\_\_\_\_  
MAILING ADDRESS 4755 Pasture Rd., Fallon, NV SW corner of 4th St. and A St  
Subdivision Name: P3-SG-01 County: Churchill  
2 LOCATION NW ¼ SW ¼ Sec 23 T 18N N/S R 3 E Latitude 39 24 27.05 N UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. 006-611-01 Longitude 118 42 14.09 W N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No. \_\_\_\_\_

3 TYPE OF WELL Is this well being plugged because a replacement well was drilled? No Is there an existing well log? NA  
 Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	1	Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (inches)	From (Feet)	To (Feet)
<u>6</u>		<u>Sch. 40</u>	<u>0</u>	<u>1</u>

7 WELL PLUGGING PROCEDURE

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why:  
The bottom of well was tagged  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used: none  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	feet

5 WATER LEVEL

Static water level NA feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

Material Used	From	feet to	feet	Neat	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured
	<u>0</u>	<u>1</u>	<u>1</u>			

6 Additional Notes or Comments  
The completion was pulled and filled with native soil grout tremied  
plug unknown well log  
NAD 27  
39.405595°N  
118.902933°W

Neat Cement Fluid Weight 1 gal lbs/gal  
Bentonite Grout % bentonite  
Date Started 1/22/2014  
Date Completed 1/22/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name National EWP Contractor  
Address 500 Main St. Woodland, CA 95695 Contractor  
Nevada contractor's license number issued by the State Contractor's Board 0075355  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2111  
Signed [Signature] By driller performing actual drilling on site or contractor  
Date 1-27-14