STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 119495
Permit No. 59654 59655
Basin 030A

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 65399

1 OWNER KINGS RIVER RANCH
MAILING ADDRESS 129 Kings River Rd
SW OROVADA, NV. 89425

ADDRESS AT WELL LOCATION KINGS RIVER RANCH
OROVADA, NV. 89425
Subdivision Name: E-6-A County: HUMBOLDT

2 LOCATION N.W. ¼ S.E. ¼ Sec 24 T 45 N/S R 33 E
PERMIT/WAIVER No. 59654/59655
Issued by Water Resources Parcel No.

Latitude N 41° 46' 01.5"
Longitude W 118° 13' 33.0"
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 84

3 TYPE OF WELL
☐ Domestic ☒ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? 117381 yes
If yes, what is replacement well NOI? 65396

Is there an existing well log? 3716
If yes, what is NDWR well log #? 117381

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
16		250'	?	

Existing Perforations:
Type of perforation UNKNOWN
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 130 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature COOL °F Quality GOOD

6 Additional Notes or Comments

We MEASURED TOTAL DEPTH AT 350'. BAD SPOT AT 168' WITH LOTS OF BOUNCING GOT PROBE TO 350'

270 BAGS BENTONITE 30/50
70 BAGS CEMENT

Nad 27
41.767186° N
118.224844° W

RECEIVED 2014 FEB -3 PM 1:11 STATE ENGINEERS OFFICE

plugs well log 3716

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: BAD SPOT AT 168' DIDNT WANT TO GET TRAPPED.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: MILLS KNIFE
From 160 feet to 5 feet Number of perfs per linear foot 4
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS
Material Used
From 350 feet to 60 feet BEN 30/50 MESH ☒ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From 60 feet to 5 feet NEAT CEMENT ☐ Pumped ☒ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured

Neat Cement Fluid Weight 12.4 - 12.6 lbs/gal 7 GALS / BAG
Bentonite Grout 30% TC % bentonite 30/50 MESH
Date Started 1-6-14
Date Completed 1-29-14

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Kings River Ranch (Contractor)
Address 129 Kings River Road (Contractor)
OROVADA, NV. 89425
Nevada contractor's license number issued by the State Contractor's Board
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1712
Signed Mike McKinch (By driller performing actual drilling on site or contractor)
Date 1-31-14

(Rev. 05-08) Replaced by log 117381

USE ADDITIONAL SHEETS IF NECESSARY