



THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

<b>LOG FOR BORING NO.</b> 137, 138		<b>JOB NAME:</b> LV PAVING			
<b>DATE STARTED</b> 1-17-14	<b>DATE COMPLETED</b>	<b>LOGGED BY</b> Ed	<b>DRILLED BY</b> Ed	<b>TYPE OF DRILL RIG</b> # 32	<b>JOB NO.</b> 6150
<b>DEPTH OF HOLE</b> 50'	<b>DIAMETER OF HOLE</b> 24"	<b>CASING</b> 8"	<b>PERFORATIONS</b> 20'	<b>SAMPLING METHOD</b>	<b>ELEVATION</b>
<b>LOCATION</b> 7+00 T 5+00				<b>DRILLERS NOTES:</b>	
<b>DEPTH</b>	<b>SAMPLES</b>	<b>GRAPHIC</b>	<b>DESCRIPTION</b>		
0'			1 silt touch of clay		
10'			1 silty clay		
20'			1 hard clay		
30'			1 silty sand & gravel Rock		
40'			1 silty clay		
50'					
60'					
70'					
80'					
90'					
100'					

DCNR/DWR/SNBO  
RECEIVED  
FEB 18 2014

**REVIEWED**  
By sphilliber at 4:32 pm, Jan 21, 2014

137, 138