

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119684  
Permit No. 54225  
Basin 218

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37184

1 OWNER Williams Jeff D. & Sharee A. ADDRESS AT WELL LOCATION 1375 E. Meranto Ave  
MAILING ADDRESS 1375 E. Meranto Ave Las Vegas, NV. 89123  
Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION NW ¼ SW ¼ Sec 23 T 22S N/S/R 61 E Latitude 36.018145 UTM E \_\_\_\_\_  NAD 27  
PERMIT/WAIVER No. R-1642 177-23-303-006 Longitude -115.133709 N \_\_\_\_\_  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? No  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? 35333

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 400 Feet Depth Cased 399 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8		.188	+1	399

Existing Perforations:

Type of perforation	Mill Slots
Size of perforation <u>1/8 x 2-1/2</u>	<u>8 rows</u>
From <u>318</u> feet to <u>399</u> feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	
From _____ feet to _____ feet	

5 WATER LEVEL  
Static water level 83 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments  
Original log = 35333  
DBB  
Pulled Pump tremied  
filled from botton to top with cement grout

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:

Type of perforator used: R-1642

From	feet to	feet	Number of perfs per linear foot
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____
From _____	feet to _____	feet	_____

8 WELL PLUGGING MATERIALS

Material Used			
From <u>0</u> feet to <u>399</u> feet	<input checked="" type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	
From _____ feet to _____ feet	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured	

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/11/2014  
Date Completed 2/11/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Eagle Drilling LLC. Contractor  
Address 7150 Placid St. Contractor  
Las Vegas NV. 89119

Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 51266  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097

Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 2/11/2014

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY

36.018145 NAD  
-115.1328806 27

DCNR/DWR/SNBO RECEIVED  
FEB 18 2014  
Permit # 54225  
STATE ENGINEERS OFFICE  
2014 MAR 14 AM 9:10