DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

Log No. 114792
Permit No.
Basin 175

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 55282

1 OWNER WINN Exploration
MAILING ADDRESS 800 N Shoreline Blvd. 19th Floor N Tower, Corpus Christi TX

ADDRESS AT WELL LOCATION Long Valley
Subdivision Name: N/A County: White Pine

2 LOCATION NW¼ SW¼ Sec T 20N N/S R 58 E/W
PERMIT/WAIVER No. OG-232 (Issued by Water Resources) Parcel No.

Latitude N 39° 35' 21.28" Longitude W 115° 23' 49.13"
UTM E N
☒ NAD 27 ☐ NAD 83/WGS 84

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☒ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NO?

Is there an existing well log? Yes
If yes, what is NDWR well log #? 100558

4 EXISTING WELL CONSTRUCTION
Depth Drilled 380 Feet Depth Cased 380 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6	12.92	.188	+1	20
6		SDR-21	20	380

Existing Perforations:
Type of perforation Screen
Size of perforation .030

From 260 feet to 280 feet
From 360 feet to 380 feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 146 feet below land surface
Artesian flow NO G.P.M. P.S.I.
Water temperature °F Quality

6 Additional Notes or Comments

This well was Plugged under Waiver Number, R-764

12-14-13 Bottom was tagged at 376, Ran 320' of 2" Trems Pipe, Pumped Approx 210 gal Neat Cement 35 Sacks No Fluid to Surface, Pulled Trems Pipe.

12-15-13 Tag Cement @ 267' Ran trems, Pumped another 38 Sacks Portland Cement Cut casing OFF @ Ground level. Plugs well log 100558 GW
Nad 27
39.589244 GW
115.396981 W

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: Well was Clean

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: NONE, Waiver # R-764

From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

Material Used

From 0 feet to 380 feet Neat Cement ☒ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured
From feet to feet ☐ Pumped ☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite

Date Started 12-14-13
Date Completed 12-15-13

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name David Gibson Contractor LLC (Contractor)
Address P.O. Box 203 Lund, NV 89317 (Contractor)
D.B.A Gibson Well Drilling
Nevada contractor's license number issued by the State Contractor's Board CC72587
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1793
Signed (By driller performing actual drilling on site or contractor)
Date 12-27-13

USE ADDITIONAL SHEETS IF NECESSARY

RECEIVED 2014 JAN -2 AM 11:15 STATE ENGINEERS OFFICE