

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 119956  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37148

1 OWNER Clark County (Pk & Comm Serv) ADDRESS AT WELL LOCATION 5483 Club House Drive  
MAILING ADDRESS 500 South Grand Central Pkwy, 2nd Floor  
Las Vegas, NV *Subdivision Name:* \_\_\_\_\_ *County:* Clark

2 LOCATION NW ¼ NE ¼ Sec 9 T 21S N/S R 62 E Latitude 36.143373 UTM E  NAD 27  
PERMIT/WAIVER No. DW-1334 16109501001 Longitude -115.052892 N  NAD 83/WGS 84  
*Issued by Water Resources* *Parcel No.*

3 **TYPE OF WELL**  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? N/A

4 **EXISTING WELL CONSTRUCTION**  
Depth Drilled 50 Feet Depth Cased 50 Feet

**EXISTING CASING SCHEDULE**

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

*Existing Perforations:*  
Type of perforation machine  
Size of perforation 0.32  
From 30 feet to 50 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 **WELL PLUGGING PROCEDURE**

Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
*Additional Perforations:*  
Type of perforator used: \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 **WATER LEVEL**  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 **WELL PLUGGING MATERIALS**

From	To	Material Used	Concrete Grout	Pumped	Poured
2	12	Concrete Grout	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
			<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

6 **Additional Notes or Comments**

DW #30

RECEIVED  
APR 19 2014

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/21/2014  
Date Completed 2/21/2014

9 **DRILLER'S CERTIFICATION**

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc  
*Contractor*  
Address 5950 Granite Lake Drive  
*Contractor*  
Granite Bay, CA 95746  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the \_\_\_\_\_  
Division of Water Resources, the on-site driller DW-2361  
Signed \_\_\_\_\_  
*By driller performing actual drilling on site or contractor*  
Date 3/28/2014

NAD  
27  
36.1434001  
-115.0520607