

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. 28		JOB NAME: LV PAVING			
DATE STARTED 1-31-14	DATE COMPLETED	LOGGED BY Ed	DRILLED BY Ed	TYPE OF DRILL RIG # 32	JOB NO. 6150
DEPTH OF HOLE 50'	DIAMETER OF HOLE 24"	CASING 8"	PERFORATIONS 2.0'	SAMPLING METHOD	ELEVATION
LOCATION Storm drain northeast side of Flamingo wash				DRILLERS NOTES:	
DEPTH	SAMPLES	GRAPHIC	DESCRIPTION		
0'			SILT. Touch of clay		
10'					
20'			Silty sand		
			SILT. Touch of clay		
30'			Red SILTY clay		
40'			hard clay		
50'					
60'					
70'					
80'					
90'					
100'					

RECEIVED
 MAR 9 7 2014

REVIEWED
 By sphilliber at 10:39 am, Feb 03, 2014

REVIEWED
 By Matt Peyrucain at 2:02 pm, Feb 03, 2014

FEB 03 2014

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. 27		JOB NAME: LU PAVING			
DATE STARTED 1-30-14	DATE COMPLETED	LOGGED BY Ed	DRILLED BY Ed	TYPE OF DRILL RIG #32	JOB NO. 6150
DEPTH OF HOLE 50'	DIAMETER OF HOLE 24"	CASING 8"	PERFORATIONS 20'	SAMPLING METHOD	ELEVATION
LOCATION in the bottom of wash. For sewer/storm East end Northside where Path Bridge was at				DRILLERS NOTES: 0-is Down in wash 20' below OG	
DEPTH	SAMPLES	GRAPHIC	DESCRIPTION		
0'			silty clay & rock		
			silty clay		
10'			Red silty clay		
20'			hard clay		
30'					
40'			silty sand & gravel		
			hard clay		
50'					
60'					
70'					
80'					
90'					
100'					

CONR/DW/SNBT
RECEIVED
MAR 8 2014

REVIEWED
By sphilliber at 10:39 am, Feb 03, 2014

REVIEWED
By Matt Peyrucain at 2:02 pm, Feb 03, 2014

FEB 03 2014