

THIS BORING LOG IS FOR VIKING'S INTERNAL PURPOSES ONLY. IT DOES NOT REPRESENT INFORMATION PROVIDED BY A SOILS ENGINEER.

LOG FOR BORING NO. ²⁶ 232425		JOB NAME: <i>LV PAVING</i>			
DATE STARTED <i>1-30-14</i>	DATE COMPLETED	LOGGED BY <i>Ed</i>	DRILLED BY <i>Ed</i>	TYPE OF DRILL RIG <i>#32</i>	JOB NO. <i>6150</i>
DEPTH OF HOLE <i>50'</i>	DIAMETER OF HOLE <i>24"</i>	CASING <i>8"</i>	PERFORATIONS <i>20'</i>	SAMPLING METHOD	ELEVATION

LOCATION *Storm drain*
At South side Flamingo wash

DRILLERS NOTES:

DEPTH	SAMPLES	GRAPHIC	DESCRIPTION
0'			<i>silt touch of clay</i>
10'			
20'		<i>▽</i>	<i>silty sand</i>
			<i>silt touch of clay</i>
30'			<i>hard clay</i>
40'			
50'			
60'			
70'			
80'			
90'			
100'			

CONCRETE RECEIVED
MAY 8 2014

REVIEWED
By sphilliber at 10:39 am, Feb 03, 2014

REVIEWED
By Matt Peyrucain at 2:02 pm, Feb 03, 2014

FEB 03 2014