

**STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT**

**OFFICE USE ONLY**  
Log No. 120197  
Permit No. \_\_\_\_\_  
Basin 212

**PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK**

*Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 37146

1 OWNER Clark County (Pk & Comm Serv) ADDRESS AT WELL LOCATION 5483 Club House Drive  
MAILING ADDRESS 500 South Grand Central Pkwy, 2nd Floor  
Las Vegas, NV Subdivision Name: \_\_\_\_\_ County: Clark

2 LOCATION SE 1/4 NE 1/4 Sec 9 T 21S N/S R 62 E Latitude 36.140259 UTM E  NAD 27  
PERMIT/WAIVER No. DW-1336 16109501001 Longitude -115.050035 N  NAD 83/WGS 84  
Issued by Water Resources Parcel No.

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? no  
If yes, what is replacement well NOI? \_\_\_\_\_  
Is there an existing well log? yes  
If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 50 Feet Depth Cased 50 Feet

EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	6	3/8	0	50

Existing Perforations:  
Type of perforation machine  
Size of perforation 0.32  
From 30 feet to 50 feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level \_\_\_\_\_ feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

				Material Used	
From <u>2</u> feet to <u>12</u> feet	Concrete Grout	<input type="checkbox"/> Pumped	<input checked="" type="checkbox"/> Poured		
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured		
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured		
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured		
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured		
From _____ feet to _____ feet		<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured		

6 Additional Notes or Comments

#5

DONOR/WSNBS RECEIVED  
APR 02 2016

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 2/20/2014  
Date Completed 2/20/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Viking Drillers Inc  
Contractor  
Address 5950 Granite Lake Drive  
Contractor  
Granite Bay, CA 95746  
Nevada contractor's license number issued by the State Contractor's Board 0034680  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller DW-2361  
Signed \_\_\_\_\_  
By driller performing actual drilling on site or contractor  
Date 3/28/2014