(Rev. 12-15)

STATE OF NEVADA
USE ADDITIONAL SHEETS IF NECESSARY
DIVISION OF WATER RESOURCES

WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 120406
Permit No. 49416
Basin 105

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 72062
WELL NAME *(if applicable)*:

1 OWNER STEVE MOTHERSELL
MAILING ADDRESS 1920 STANDIFORD AVE
MODESTO, CA 95350

ADDRESS AT WELL LOCATION EAST VALLEY RD AND KRISTY LANE
GARDNERVILLE, NV 89410
Subdivision Name: *County:* Douglas

2 LOCATION SW ¼ SE ¼ Sec 23 T 13N N/S R 20 E
PERMIT/WAIVER No. 49416 N/A
Issued by Water Resources *Parcel No.*

Latitude 38.969834*N
Longitude 119.704828*W
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☒ Test
☒ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NOI?

Is there an existing well log? YES
If yes, what is NDWR well log #? 27673

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled 34 Feet Depth Cased 34 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8	15.65	.188	+1	34

Existing Perforations:
Type of perforation N/A
Size of perforation N/A

From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 *WATER LEVEL*
Static water level 32 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature N/A °F Quality N/A

6 Additional Notes or Comments

WELL WAS ABANDONED YEARS AGO AND SETTLED DOWN TO 34'. WE TOPPED OFF THE CEMENT FROM SURFACE TO 34' AND CUT OFF CASING AND BURIED.

Plugging test well log # 27673
NAD27
38.969826°N
119.703819°W

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: N/A

From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	Material Used		
0	34	CEMENT GROUT	☐ Pumped	☒ Poured
			☐ Pumped	☐ Poured
			☐ Pumped	☐ Poured
			☐ Pumped	☐ Poured
			☐ Pumped	☐ Poured
			☐ Pumped	☐ Poured

Neat Cement Fluid Weight 94/4 lbs/gal
Bentonite Grout % bentonite

Date Started 23-Jun
Date Completed 23-Jun

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name CAPITAL CITY WELL DRILLING AND PUMP SERVICE INC.
Contractor
Address 20 KIT KAT DRIVE
Contractor
CARSON CITY, NV 89706

Nevada contractor's license number
Issued by the *State Contractor's Board* 0055548
Nevada driller's license number issued by the
Division of Water Resources, the *on-site driller* 1905
Signed
By driller performing actual drilling on site or contractor
Date 6/28/2014

2014 JUL 1 PM 1:10