STATE OF NEVADA
DIVISION OF WATER RESOURCES
# WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 120462
Permit No.
Basin 107

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

*Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340*

NOTICE OF INTENT NO. 70188

1 OWNER Rightway Investments LLC.
MAILING ADDRESS 6121 Lakeside Drive Reno, Nevada 89511

ADDRESS AT WELL LOCATION Artesia Ranch
Subdivision Name: County: Lyon

2 LOCATION SE ¼ SW ¼ Sec 24 T 13N N/S R 23 E
PERMIT/WAIVER No. ~~71053~~ (Issued by Water Resources) R-816 Parcel No.
Latitude 38° 58.368 N
Longitude 119° 21.500 W
UTM E N
☐ NAD 27 ☒ NAD 83/WGS 84

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? Yes
If yes, what is replacement well NOI? 70186

Is there an existing well log? Unknown
If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION
Depth Drilled ? Feet Depth Cased ? Feet

EXISTING CASING SCHEDULE

| Size O.D. (Inches) | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
|---|---|---|---|---|
| 6" | | .188" | +2' | 29' |
| | | | | |
| | | | | |
| | | | | |

Existing Perforations:
Type of perforation N/A
Size of perforation N/A
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level Dry feet below land surface
Artesian flow No G.P.M. 0 P.S.I
Water temperature N/A °F Quality

6 Additional Notes or Comments

NAD 27
38.972886°N
119.357341°W

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why:
There was a waiver filed with the office explaining why this well was not cleaned out to total depth.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: N/A
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

| From | feet to | feet | Material Used | Pumped | Poured |
|---|---|---|---|---|---|
| 0' | 29' | | Neat Cement | ☐ | ☒ |
| | | | | ☐ | ☐ |
| | | | | ☐ | ☐ |
| | | | | ☐ | ☐ |
| | | | | ☐ | ☐ |
| | | | | ☐ | ☐ |

Neat Cement Fluid Weight 15 lbs lbs/gal
Bentonite Grout % bentonite
Date Started 7/8/2014
Date Completed 7/8/2014

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Stonehouse Drilling and Construction LLC. (Contractor)
Address 7801 Lakeside Drive (Contractor)
Reno, Nevada 89511
Nevada contractor's license number issued by the *State Contractor's Board* 0069994
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* #2158
Signed (By driller performing actual drilling on site or contractor)
Date 7/17/14

(Rev. 05-06)

USE ADDITIONAL SHEETS IF NECESSARY