

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 121334  
Permit No. \_\_\_\_\_  
Basin 045

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 71658

WELL NAME (if applicable): \_\_\_\_\_

1 OWNER SHARON SCHOLLARS  
MAILING ADDRESS 170 ROCKING CHAIR RD #4  
SPRING CREEK, NV 89815

ADDRESS AT WELL LOCATION 343 BAR NONE LN

Subdivision Name: PLEASANT VALLEY County: ELKO

2 LOCATION SW ¼ NE ¼ Sec 26 T 33N N/S R 57 E  
PERMIT/WAIVER No. R-828 023-020-010  
Issued by Water Resources Parcel No.

Latitude UTM E 0625428  NAD 27  
Longitude N 4508162  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? YES  
If yes, what is replacement well NO? 71657

Is there an existing well log? UNKNOWN  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled \_\_\_\_\_ Feet Depth Cased \_\_\_\_\_ Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no

| EXISTING CASING SCHEDULE |                     |                         |             |           |
|--------------------------|---------------------|-------------------------|-------------|-----------|
| Size O.D. (Inches)       | Weight/Ft. (Pounds) | Wall Thickness (Inches) | From (Feet) | To (Feet) |
| 6.625                    | 13                  | .188                    | 0           | ?         |
|                          |                     |                         |             |           |
|                          |                     |                         |             |           |

If well was not cleaned out to total depth, please explain why: A SHOP WAS BUILT OVER THE WELL- THE WELL HEAD WAS INSIDE OF THE SHOP

Existing Perforations:  
Type of perforation \_\_\_\_\_  
Size of perforation \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: \_\_\_\_\_ feet to \_\_\_\_\_ feet  
Was the casing over drilled?  yes  no

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level >124 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

6 Additional Notes or Comments

WELL WAS MEASURED TO A DEPTH OF 124'  
DRY HOLE, NO WATER IN THE WELL

MEASURED WELL CASING THICKNESS @ SURFACE

2014-11-10 11:20  
40.716737° N  
115.515017° W  
NAD 83

8 WELL PLUGGING MATERIALS

Material Used  
From 0 feet to 124 feet NEAT CEMENT  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

Neat Cement Fluid Weight 15 lbs/gal  
Bentonite Grout 3 % bentonite

Date Started 11/10/2014  
Date Completed 11/10/2014

9 DRILLER'S CERTIFICATION

This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name HACKWORTH DRILLING INC. Contractor  
Address P.O. BOX 850 Contractor  
ELKO, NV 89803

Nevada contractor's license number issued by the State Contractor's Board 020582

Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1408

Signed [Signature] By driller performing actual drilling on site or contractor

Date 11/10/2014

*Plugging Unknown Well log*