

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. **121457**  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. **37248**  
WELL NAME (if applicable): **MW-4**

1 OWNER **Circle K Stores Inc.**  
MAILING ADDRESS **P.O. Box 52085 DC-17**  
**Phoenix, Az 85072-2085**

ADDRESS AT WELL LOCATION **4380 E. Bonanza Rd.**  
**Las Vegas, Nv 89110**  
Subdivision Name \_\_\_\_\_ County: **Clark**

2 LOCATION SE ¼ SE ¼ Sec 30 T 20S N/S R 62 E  
PERMIT/WAIVER No. **140-30-803-011**  
Issued by Water Resources Parcel No.

Latitude **36.173751** UTM E  NAD 27  
Longitude **-115.080676** N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? **NO**  
Is there an existing well log? \_\_\_\_\_  
If yes, what is replacement well NOI? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	25	Feet
EXISTING CASING SCHEDULE				
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
4	PVC	SCH 40	0	25

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no If pulled from: **0** feet to **25** feet  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made: \_\_\_\_\_

Existing Perforations:

Type of perforation	Size of perforation	From	feet to	To	feet
MACHINE SLOTTED	0.02	10	feet to	25	feet
			feet to		feet
			feet to		feet
			feet to		feet
			feet to		feet

Additional Perforations:

Type of perforator used:	From	feet to	feet	Number of perfs per linear foot

5 WATER LEVEL  
Static water level **17** feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

From	feet to	feet	Number of perfs per linear foot


6 Additional Notes or Comments

**\*DRENIED FROM BOTTOM TO TOP W/ BENTONITE GROUT\***

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used	<input type="checkbox"/> Pumped	<input type="checkbox"/> Poured
25	feet to	0	BENTONITE GROUT	<input checked="" type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>
	feet to			<input type="checkbox"/>	<input type="checkbox"/>

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout **28** % bentonite  
Date Started **10/15/2014**  
Date Completed **10/15/2014**

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name **EAGLE DRILLING SERVICES, LLC.**  
Contractor  
Address **7150 Placid St. Las Vegas, Nv 89119**  
Contractor  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board **51266**  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller **2490-LTD**  
Signed   
By driller performing actual drilling on site or contractor  
Date **11/4/2014**

36.1737794 NAD  
-115.0793431 27