

well log# 121758



Stantec Consulting Services Inc.
1165 East Jennings Way, Suite 101
Elko, NV 89801-7977
Tel: (775) 738-8766
Fax: (775) 738-2264


595 Double Eagle Court, Suite 2000
Reno, NV 89521-9005
Tel: (775) 747-5777
Fax: (775) 747-2177

**Valmy Power Plant
Summary Log of Replacement Monitoring Well**

LF-4RR: Completed 01/28/2015

Well Number	From	To	Interval	Lithology	Groundwater
LF-4RR	0	3.5	3.5	Poorly graded sand	--
	3.5	10	6.5	Silty sand with gravel	--
	10	18	8	Clayey sands	--
	18	32	14	Silt with sand layers	--
	32	69	37	Lean clay with sand	--
	69	79	10	Clayey gravel with sand	Water at approximately 70 feet
	79	90	11	Basalt	--

Notes: All intervals in feet below ground surface.
Groundwater depth as first encountered in drilling.



Walter M. Martin
Walter Martin, CPG-11358

2/11/15
Date

RECEIVED
2015 FEB 13 AM 11:29
SAS ENGINEERS OFFICE