

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 123296  
Permit No. \_\_\_\_\_  
Basin \_\_\_\_\_

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in  
accordance with NRS 534.170 and NAC 534.340

1 OWNER DR. HORTON ADDRESS AT WELL LOCATION West Well 3540 E. Tompkins Ave.  
MAILING ADDRESS 1801 Whitney Ranch DR Henderson NV 89169 Subdivision Name: \_\_\_\_\_ County: CLARK  
2 LOCATION NW 1/4 SW 1/4 Sec 19 T 21 N R 62 E Latitude 36.104084 UTM E  NAD 27  
PERMIT/WAIVER No. 169-19301-024 Longitude -115.098736 N  NAD 83/WGS 84  
Issued by Water Resources \_\_\_\_\_ Parcel No. \_\_\_\_\_

3 TYPE OF WELL  Domestic  Irrigation  Test  Municipal/Industrial  Monitor  Stock  
Is this well being plugged because a replacement well was drilled? NO  
Is there an existing well log? yes  
If yes, what is replacement well NOI? \_\_\_\_\_ If yes, what is NDWR well log #? 59075

4 EXISTING WELL CONSTRUCTION

Depth Drilled	Feet	Depth Cased	Feet
EXISTING CASING SCHEDULE			
Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	To (Feet)
<u>8 5/8</u>		<u>.134</u>	<u>+2 250</u>

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: pipe let parts collapse Deteriorated  
Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no  
If casing was left in place, please show where additional perforations were made:  
Additional Perforations: AIR PERFORATOR  
Type of perforator used: AIR PERFORATOR

Existing Perforations:  
Type of perforation Pipe Deteriorated AWAY  
Size of perforation \_\_\_\_\_

From	feet to	feet
From	feet to	feet

5 WATER LEVEL  
Static water level 20 feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS

From	feet to	Material Used	Pumped	Poured
From <u>0</u>	feet to <u>NEAT</u>	<u>CEMENT</u>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>
From _____	feet to _____	_____	<input type="checkbox"/>	<input type="checkbox"/>

6 Additional Notes or Comments  
AIR PERFORATOR did NOT touch ANY THING.  
Pipe was Rusted AWAY

Neat Cement Fluid Weight \_\_\_\_\_ lbs/gal  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started AUG. 24-15  
Date Completed AUG. 24-15

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name VERNON H. DIMICK Contractor  
Address 13040 HORSE DR. LV. NV. 89166 Contractor  
Nevada contractor's license number \_\_\_\_\_  
issued by the State Contractor's Board 10062  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 552  
Signed V.H. Dimick By driller performing actual drilling on-site or contractor  
Date 8-24-15