

STATE OF NEVADA  
DIVISION OF WATER RESOURCES  
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY  
Log No. 123588  
Permit No. \_\_\_\_\_  
Basin 087

PRINT OR TYPE ONLY  
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 70128

1 OWNER Shell Oil Products  
MAILING ADDRESS 20945 S. Wilmington Ave  
SW Carson, CA 90810

ADDRESS AT WELL LOCATION 75 W. Plumb Lane  
Primm, NV  
Subdivision Name: \_\_\_\_\_ County: Washoe

2 LOCATION SW 1/4 Sec 24 T 19 N R 19 E  
PERMIT/WAIVER No. \_\_\_\_\_  
Issued by Water Resources Parcel No. S. OF 014-251-54, N. OF 019-51-09

Latitude 39° 30.749' N UTM E  NAD 27  
Longitude 119° 48.335' W N  NAD 83/WGS 84

3 TYPE OF WELL  
 Domestic  Irrigation  Test  
 Municipal/Industrial  Monitor  Stock

Is this well being plugged because a replacement well was drilled? NO  
Is there an existing well log? NO  
If yes, what is replacement well NOI? \_\_\_\_\_  
If yes, what is NDWR well log #? \_\_\_\_\_

4 EXISTING WELL CONSTRUCTION  
Depth Drilled 28 Feet Depth Cased 28 Feet

7 WELL PLUGGING PROCEDURE  
Was well cleaned out to total depth?  yes  no  
If well was not cleaned out to total depth, please explain why: \_\_\_\_\_

Size-O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
<u>2</u>		<u>SCH. 40</u>	<u>0</u>	<u>28</u>

Was the well contaminated?  yes  no  
Was the casing pulled?  yes  no  
Was the casing over drilled?  yes  no

Existing Perforations:  
Type of perforation Manufactured  
Size of perforation 1.020  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet

If casing was left in place, please show where additional perforations were made:  
Additional Perforations:  
Type of perforator used:  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet Number of perfs per linear foot \_\_\_\_\_

5 WATER LEVEL  
Static water level NONE feet below land surface  
Artesian flow \_\_\_\_\_ G.P.M. \_\_\_\_\_ P.S.I.  
Water temperature \_\_\_\_\_ °F Quality \_\_\_\_\_

8 WELL PLUGGING MATERIALS  
Material Used  
From 0 feet to 28 feet Neat Cement  Pumped  Poured  
From \_\_\_\_\_ feet to \_\_\_\_\_ feet  Pumped  Poured

6 Additional Notes or Comments  
Abandoned by pressure grouting  
Applied 25 p.s.i. for 5 minutes  
NAD 27  
39.505817  
119.805583

Neat Cement Fluid Weight 47 lbs/gal 3  
Bentonite Grout \_\_\_\_\_ % bentonite  
Date Started 9.9.15  
Date Completed 9.9.15

9 DRILLER'S CERTIFICATION  
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.  
Name Gregg Drilling + Testing Contractor  
Address 950 Hawk Rd, Martinez, CA 94533 Contractor  
Nevada contractor's license number issued by the State Contractor's Board CA3-DD3843  
Nevada driller's license number issued by the Division of Water Resources, the on-site driller \_\_\_\_\_  
Signed Jan Hill  
Date \_\_\_\_\_  
Driller performing actual drilling on site or contractor

RECEIVED  
DIVISION OF WATER RESOURCES  
OFFICE  
SEP 11 2015  
AM 11:21

(Rev. 05-09)

USE ADDITIONAL SHEETS IF NECESSARY

Plugging unknown well log