STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 125015
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 38929
WELL NAME (If applicable): MW-8

1 OWNER County Of Clark
MAILING ADDRESS 500 S. Grand Central Pkwy.
Las Vegas, NV 89155

ADDRESS AT WELL LOCATION Public Right Of Way
(Las Vegas Blvd N & Lake Mead Blvd)
Subdivision Name: County: Clark

2 LOCATION SE ¼ NW ¼ Sec 23 T 20S N/S R 61 E
PERMIT/WAIVER No. (Issued by Water Resources) Parcel No. 139-23-299-035

Latitude 36.196435
Longitude -115.128163
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☐ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☒ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? NO
If yes, what is replacement well NO!?

Is there an existing well log?
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased 26 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2	PVC	.020		

Existing Perforations:
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 17 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 77 °F Quality

6 Additional Notes or Comments

WHILE PULLING. THE CASING BROKE OFF AT 3 FEET BELOW GROUND. KNOCKED OUT BOTTOM AND GROUTED FROM BOTTOM TO TOP

DCNR/DWR/SNBC
RECEIVED
FEB 19 2016

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used:
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

				Material Used		
From 26	feet to 1	feet	BENTONITE GROUT	☒ Pumped	☐ Poured
From 1	feet to 0	feet	CONCRETE	☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout 28 % bentonite

Date Started 2/12/2016
Date Completed 2/12/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name EAGLE DRILLING SERVICES
Contractor
Address 7150 PLACID ST LAS VEGAS, NV 89119
Contractor

Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2490-LTD
Signed
By driller performing actual drilling on site or contractor
Date 2/12/2016

(Rev. 12-13)
USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

36.1964649
-115.1273283