STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 12513 6
Permit No.
Basin 086

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO 67297
WELL NAME *(if applicable)*:

1 OWNER Jauron Family LLC
MAILING ADDRESS 6960 Eagle Creek Ct.
Reno, NV 89519

ADDRESS AT WELL LOCATION 5160 Carol St.
Sun Valley, NV
Subdivision Name: *County:* Washoe

2 LOCATION SW ¼ SE ¼ Sec 19 T 20N N/S R 20 E
PERMIT/WAIVER No. R-920 085-852-14
Issued by Water Resources *Parcel No.*

Latitude 39.5805 UTM E ☐ NAD 27
Longitude 1197768 N ☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? No
If yes, what is replacement well NOI?

Is there an existing well log? No
If yes, what is NDWR well log #?

4 *EXISTING WELL CONSTRUCTION*
Depth Drilled Feet Depth Cased 78 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
2		.25	0	78

Existing Perforations.
Type of perforation Unknown
Size of perforation Unknown

From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to

5 *WATER LEVEL*
Static water level 2' feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments
We abandoned this well by installing trime pipe and pumping neat cement from the bottom to the surface. We were unable to pull 2" pipe, we believe it to be cemented in place.....

Washoe County Permit # WL160071

NAD 27
39.580589
119.775777

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☒ yes ☐ no
If well was not cleaned out to total depth, please explain why:

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforater used: None

From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used		
0	78		Neat Cement	☒ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured

Neat Cement Fluid Weight 15 lbs/gal
Bentonite Grout % bentonite
Date Started 6/23/2016
Date Completed 6/23/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name Fundin Pump & Well Service
Contractor
Address 4030 Eastlake Blvd. Washoe Valley, NV 89704
Contractor
Phone 775-849-1027

Nevada contractor's license number issued by the *State Contractor's Board* 74720
Nevada driller's license number issued by the Division of Water Resources, the *on-site driller* 2205
Signed Norm L Fundin
By driller performing actual drilling on site or contractor
Date 6/27/2016

[Rev. 04-15] USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

Plugging unknown well log