STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 125693
Permit No.
Basin

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 39000
WELL NAME (If applicable)

1 OWNER Richmond American Homes Nevada inc %B Walsh
MAILING ADDRESS 7770 sDean Martin Dr
Las Vegas Nv 89139

ADDRESS AT WELL LOCATION Sheleheda Ave.
Las Vegas NV
Subdivision Name. County Clark

2 LOCATION SE ¼ SW ¼ Sec 1 T 19S N/S R 60 E
PERMIT/WAIVER No. R-1723 (Issued by Water Resources) 125-01-418-041 (Parcel No.)
Latitude 36.323849
Longitude -115.217588
UTM E
N
☐ NAD 27 ☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled?
If yes, what is replacement well NO?

Is there an existing well log? yes
If yes, what is NDWR well log #? 53154

4 EXISTING WELL CONSTRUCTION
Depth Drilled 300 Feet Depth Cased 300 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8			0	300

Existing Perforations
Type of perforation
Size of perforation
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 130 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 78 °F Quality

6 Additional Notes or Comments

Filled with cement Grout
Tremied From Bottom to Top

DCNR/DWR/SNBO
RECEIVED
AUG 02 2016

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why:
there was no draw pipe or pump in well but was at 90' we drilled debris out to 160' and hit hard debris with bound up our drill rig

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations
Type of perforater used: R-1723

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used		
From 0	feet to 160	feet		☒ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite

Date Started 7/11/2016
Date Completed 7/29/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services (Contractor)
Address 7150 Placid Steet (Contractor)
Las Vegas Nv

Nevada contractor's license number issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on site driller 2097
Signed (By driller performing actual drilling on site or contractor)
Date 7/29/2016

(Rev 12-12) USE ADDITIONAL SHEETS IF NECESSARY pg. of pg.

NAD 27 36.3238824
-115.216748