

STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 125705
Permit No. _____
Basin _____

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in
accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 38957
WELL NAME (if applicable) W2

1 OWNER Big tip Etal cousumano sharon ADDRESS AT WELL LOCATION 5145bronco
MAILING ADDRESS 8375 w Flamingo Rd Las Vegas Nv
Las Vegas Nv 89147 Las Vegas Nv
Subdivision Name _____ County _____ Clark

2 LOCATION NE 1/4 SE 1/4 Sec 35 T 19S N/S R 60 E Latitude 36.25292 UTM E NAD 27
PERMIT/WAIVER No. R-1719 125-35-701-006 Longitude -115.228148 N NAD 83/WGS 84
Issued by Water Resources Parcel No _____

3 TYPE OF WELL Domestic Irrigation Test
 Municipal/Industrial Monitor Stock
Is this well being plugged because a replacement well was drilled? no
If yes, what is replacement well NOI? _____
Is there an existing well log? yes
If yes, what is NDWR well log #? 60588

4 EXISTING WELL CONSTRUCTION
Depth Drilled 410 Feet Depth Cased 400 Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
8			0	400

Existing Perforations
Type of perforation saw cut double perforatn
Size of perforation
From 240 feet to 400 feet
From _____ feet to _____ feet
From _____ feet to _____ feet
From _____ feet to _____ feet

5 WATER LEVEL
Static water level 175 feet below land surface
Artesian flow _____ G.P.M. P.S.I.
Water temperature 78 °F Quality _____

6 Additional Notes or Comments

Filled with cement Grout
Tremled From Bottom to Top

Neat Cement Fluid Weight _____ lbs/gal
Bentonite Grout _____ % bentonite

Date Started 6/6/2016
Date Completed 6/21/2016

DCNR/DWR/SNBO
RECEIVED
JUN 28 2016

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? yes no
If well was not cleaned out to total depth, please explain why: _____

Was the well contaminated? yes no
Was the casing pulled? yes no If pulled from: _____ feet to _____ feet
Was the casing over drilled? yes no
If casing was left in place, please show where additional perforations were made:
Additional Perforations _____

Type of perforater used: R-1719
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____
From _____ feet to _____ feet Number of perfs per linear foot _____

8 WELL PLUGGING MATERIALS

Material Used
From 0 feet to 390 feet Pumped Poured
From _____ feet to _____ feet Pumped Poured

DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Eagle Drilling Services
Contractor
Address 7150 Placid Steet
Contractor
Las Vegas Nv

Nevada contractor's license number _____
Issued by the State Contractor's Board 51266
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2097
Signed _____
By driller performing actual drilling on site or contractor
Date 6/21/2016

NAD 27 36.2529532
-115.2273092