STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 125799
Permit No.
Basin 103

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 74968
WELL NAME (if applicable):

1 OWNER RALPH RICHARDSON
MAILING ADDRESS 2060 PINION HILLS RD
CARSON CITY, NV 89706

ADDRESS AT WELL LOCATION 2060 PINION HILLS RD
CARSON CITY, NV 89706
Subdivision Name:
County: Carson

2 LOCATION NW ¼ SE ¼ Sec 23 T 15N N/S R 20 E
PERMIT/WAIVER No. 010-10-111
Issued by Water Resources Parcel No

Latitude 39.148448*N
Longitude 119.703005*W
UTM E
N
☐ NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? YES
If yes, what is replacement well NO? 74968

Is there an existing well log? NO
If yes, what is NDWR well log #? N/A

4 EXISTING WELL CONSTRUCTION
Depth Drilled Feet Depth Cased Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 5/8	.8.95	.75	0	125

Existing Perforations:
Type of perforation N/A
Size of perforation N/A
From N/A feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level 95 feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature 110 °F Quality BAD

6 Additional Notes or Comments

WELL CAS CONSTRUCTED WITH STOVE PIPE BACK YEARS AGO, WHEN PUMP WAS PULLED OUT THE CASING COLLASPED IN AND CLOGGED OFF THE WELL WELL IS INSIDE OF A GARAGE IN THE FLOOR.

2016 AUG 29 AM 11:47
RECEIVED
DIVISION OF WATER RESOURCES

NAD 27
39.148538
119.701994

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why:
WELL COLLASPED AT THE 25' MARK, WELL WAS INSTALLED WITH STOVE PIPE AND IT RUSTED OUT AND FELL IN WELL.

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:
Additional Perforations:
Type of perforator used: N/A
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot
From feet to feet Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

From	feet to	feet	Material Used		
0	25		NEAT CEMENT	☒ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured
				☐ Pumped	☐ Poured

Neat Cement Fluid Weight 94/4 lbs/gal
Bentonite Grout % bentonite
Date Started 8/8/2016
Date Completed 8/8/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.
Name CAPITAL CITY WELL DRILLING AND PUMP SERVICE INC. (Contractor)
Address 20 KIT KAT DRIVE CARSON CITY, NV 89706 (Contractor)
Phone
Nevada contractor's license number issued by the State Contractor's Board 0055548
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 1905
Signed (By driller performing actual drilling on site or contractor)
Date 8/15/20166 5/8

(Rev. 04-16)

USE ADDITIONAL SHEETS IF NECESSARY

pg. of pg.

Plugging unknown well log